



First Source Inc
1100 Iverleigh Trail
Charlotte, North Carolina 28270
fsimedicalimaging.com

Phone: 800-349-5980
704-845-3049
Fax: 704-845-3069
firstsourceimage@aol.com

First Source 8900 Dryview Training Course Outline

Day 1 8900 DryView Overview

- 1) Overview and Marketplace
- 2) Resource Material
- 3) Operating the 8900
- 4) Theory of operation
 - a. Component ID and Function
 - b. Module Removal / Problem ID / Installation

Day 2 8900 DryView Service Software/PM/Adjustments

- 5) Review and Troubleshooting
- 6) Service Communication Software
 - a. Securelink Authentication
 - b. Weblink Application
 - c. Connection Overview/Demonstration
- 7) Preventive Maintenance Procedure
 - a. 20K / 40K/ 100K PM
 - b. Parts Services Overview
- 8) Imager Adjustments

Day 3 8900 DryView System Fundamentals

- 9) Review and Troubleshooting
- 10) MCS overview and component theory
 - a. DRE Computer
 - b. EBA / MCS / Bus Components
- 11) 8900 Base configuration
 - a. Backup/Restore
 - b. Software Installation
 - c. Accessories Installation / Configuration

Day 4 DICOM Review //MIM 100E, 200E Overview

- 12) Review and Troubleshooting
- 13) DICOM Discussion and Review
- 14) MIM E series overview
- 15) DICOM Print Server Software Installation and Configuration
- 16) Modality Server Software Installation and Configuration

Day 5 MIM Fundamentals / Course Review

- 17) Review and Troubleshooting
- 18) Special DICOM Tools Installation and Training
- 19) Troubleshooting / Repair / Wrapup Review