



First Source Inc
1100 Iverleigh Trail
Charlotte, North Carolina 28270
fsimedicalimaging.com

Phone: 800-349-5980
704-845-3049
Fax: 704-845-3069
firstsourceimage@aol.com

First Source Dryview Training Course Outline

Day 1 8700 DryView Overview

- 1) Overview and Marketplace
- 2) Resource Material
- 3) Operating the 8700
- 4) Theory of operation (Ride on film by module)
 - a. Component ID
 - b. Removal of Modules
 - c. Associated Problems
 - d. Installation of Modules

Day 2 8700 DryView Adjustments/PM

- 5) Review and Troubleshooting
- 6) System Electronics
 - a. ID and Purpose of all PCB's
- 7) Service Communication Software
 - a. Configuration Overview
 - b. Diagnostics Overview
 - c. Adjustments Overview
- 8) Preventive Maintenance Procedure
 - a. 10K/30K
 - b. Parts Services Overview
- 9) Printer Adjustments

Day 3 8700 DryView Direct Connectivity

- 9) Overview
- 10) Configuration
- 11) Connectivity
 - a. EIB Configuration/Setup
- 12) Analog Installation Lab

Day 4 DICOM Basics/9410/MIM Overview

- 13) DICOM Introduction
- 14) DICOM/9410 PacsLink/MIM Products
- 15) Print Server Installation and Configuration
- 16) Modality Server Installation and Configuration

Day 5 MIM Fundamentals / Course Review

- 17) Print Server Installation and Configuration
- 18) Modality Server Installation and Configuration
- 19) Wrap-up and Q & A